

Fire & Safety Industries

Golden Rules



- I will ALWAYS stop work that is unsafe.
- I will ALWAYS isolate ALL energy sources, apply my personal isolation lock, my personal danger tag and 'test for dead' before working on any plant or equipment.
- I will always report to an onsite Supervisor and participate in pre-start or safety discussion before commencing work at any mine site.
- I will never conduct work without a pre-job risk assessment appropriate to the level of risk involved for my task and will always follow FSI and Principal Contracts Policies and Procedures.
- I will never position myself under a suspended load or between a suspended load and fixed objects.
- I will always ensure I am appropriately licensed, trained, competent, and authorised before carrying out any work or operating any equipment.
- I will never overtake surface mining equipment, or enter within their minimum approach distance, without positive radio communication.
- I will never attend work fatigued or under the influence of alcohol or drugs.
- I will always ensure my vehicle, equipment and plant is maintained in a good condition and report all defects.

For more information and detailed guidance visit
www.fireandsafety.com.au

